EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(transfer adj value adj d99)	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:36
2	1	(transfer near10 d99)	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:36
L3	2	(transfer adj value adj "d. sub.99")	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:38
_4	2	(transfer near10 "d.sub.99")	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:41
_5	0	4 not 3	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:41
L6	91	"d.sub.99"	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:41
L7	1632	mastersizer	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:43
L8	97	7 and ((particle or particulate) near10 (conductive or conducting))	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:45
L9	12	8 and weld\$4	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:46
L10	7080	427/384,385.5,388.1-388.5. ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:53
L11	240	10 and ((particle or particulate or powder or flake) near10 (conductive or conducting))	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:55
L12	5479	10 and (resin or polymer\$4 or binder)	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:55
L13	101	10 and (weld\$4 near10 coat \$4)	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:56
L14	15	11 and 12 and 13	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:56
L15	15	14 not (4 or 9)	US-PGPUB; USPAT; USOCR	OR	ON	2008/02/06 13:57
L16	42329	((particle or particulate or powder or flake) near10 (conductive or conducting))	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/06 14:05
L17	2826528	(resin or polymer\$4 or binder)	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/06 14:05
L18	12426	(weld\$4 near10 coat\$4)	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/06 14:06

L19		16 and 17 and 18	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/06 14:06
L20	20	19 and zinc	FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/06 14:08

2/6/08 2:21:04 PM

C:\ Documents and Settings\ ECameron1\ My Documents\ EAST\ Workspaces\ 10511222b.wsp